



DESCRIPTION AND SIZE	CARTON QUANTITY	Weight Lbs/ M
FULLY THREADED HEX MACHINE BOLTS, ASTM A307, ZP		
1/4-20 X 1/2	4000	12.2
1/4-20 X 5/8	3500	13.1
1/4-20 X 3/4	3000	14.9
1/4-20 X 1	2500	16.2
1/4-20 X 1 1/4	2300	18.4
1/4-20 X 1 1/2	2000	21.2
1/4-20 X 1 3/4	1800	23.2
1/4-20 X 2	1500	26.9
1/4-20 X 2 1/4	1400	29.6
1/4-20 X 2 1/2	1300	32.4
1/4-20 X 2 3/4	1200	35.0
1/4-20 X 3	1000	37.4
1/4-20 X 3 1/4	900	47.7
1/4-20 X 3 1/2	850	51.9
1/4-20 X 3 3/4	800	44.8
1/4-20 X 4	675	58.8
1/4-20 X 4 1/2	650	65.7
1/4-20 X 5	500	72.6
1/4-20 X 5 1/2	400	79.5
1/4-20 X 6	350	86.4
5/16-18 X 1/2	2500	19.9
5/16-18 X 5/8	2000	22.0
5/16-18 X 3/4	2000	24.2
5/16-18 X 1	1500	28.7
5/16-18 X 1 1/4	1200	32.8
5/16-18 X 1 1/2	1200	36.9
5/16-18 X 1 3/4	1000	41.0
5/16-18 X 2	900	44.9
5/16-18 X 2 1/4	800	49.4
5/16-18 X 2 1/2	800	53.0
5/16-18 X 2 3/4	700	57.6
5/16-18 X 3	650	61.7
5/16-18 X 3 1/4	600	65.0
5/16-18 X 3 1/2	600	82.1
5/16-18 X 3 3/4	500	73.4
5/16-18 X 4	500	92.9
5/16-18 X 4 1/2	450	103.7
5/16-18 X 5	400	114.4
5/16-18 X 5 1/2	400	103.6
5/16-18 X 6	350	135.9
3/8-16 X 1/2	1500	29.3
3/8-16 X 5/8	1500	32.4
3/8-16 X 3/4	1200	35.5
3/8-16 X 1	1000	41.8
3/8-16 X 1 1/4	900	47.0
3/8-16 X 1 1/2	800	53.2
3/8-16 X 1 3/4	700	59.3
3/8-16 X 2	600	65.6
3/8-16 X 2 1/4	600	72.3

DESCRIPTION AND SIZE	CARTON QUANTITY	Weight Lbs/ M
FULLY THREADED HEX MACHINE BOLTS, ASTM A307, ZP		
3/8-16 X 2 1/2	500	77.5
3/8-16 X 2 3/4	450	83.9
3/8-16 X 3	450	90.0
3/8-16 X 3 1/4	450	93.9
3/8-16 X 3 1/2	400	102.5
3/8-16 X 3 3/4	400	107.3
3/8-16 X 4	350	116.7
3/8-16 X 4 1/2	300	127.8
3/8-16 X 5	250	140.0
3/8-16 X 5 1/2	250	155.0
3/8-16 X 6	250	162.1
7/16-14 X 1 1/4	700	65.7
7/16-14 X 1 1/2	600	74.2
7/16-14 X 1 3/4	500	82.1
7/16-14 X 2	450	90.1
7/16-14 X 2 1/4	400	98.3
7/16-14 X 2 1/2	400	107.2
7/16-14 X 2 3/4	400	115.6
7/16-14 X 3	300	124.3
7/16-14 X 3 1/2	250	140.1
7/16-14 X 4	250	184.1
1/2-13 X 3/4	500	76.3
1/2-13 X 1	500	83.3
1/2-13 X 1 1/4	450	94.3
1/2-13 X 1 1/2	400	106.7
1/2-13 X 1 3/4	350	118.8
1/2-13 X 2	350	129.3
1/2-13 X 2 1/4	300	140.0
1/2-13 X 2 1/2	275	150.9
1/2-13 X 2 3/4	250	164.0
1/2-13 X 3	250	175.0
1/2-13 X 3 1/4	200	183.6
1/2-13 X 3 1/2	200	196.7
1/2-13 X 3 3/4	200	205.2
1/2-13 X 4	180	216.3
1/2-13 X 4 1/2	160	241.5
1/2-13 X 5	150	261.8
1/2-13 X 5 1/2	130	284.0
1/2-13 X 6	120	305.0
5/8-11 X 1	300	146.5
5/8-11 X 1 1/4	250	165.5
5/8-11 X 1 1/2	200	184.3
5/8-11 X 1 3/4	200	198.7
5/8-11 X 2	200	215.8
5/8-11 X 2 1/4	160	240.0
5/8-11 X 2 1/2	160	254.8
5/8-11 X 2 3/4	160	271.7
5/8-11 X 3	150	290.8
5/8-11 X 3 1/4	150	306.0



DESCRIPTION AND SIZE	CARTON QUANTITY	Weight Lbs/ M
FULLY THREADED HEX MACHINE BOLTS, ASTM A307, ZP		
5/8-11 X 3 1/2	120	330.4
5/8-11 X 3 3/4	120	338.3
5/8-11 X 4	120	362.0
5/8-11 X 4 1/2	100	443.7
5/8-11 X 5	100	486.8
5/8-11 X 5 1/2	80	467.3
5/8-11 X 6	80	573.0
3/4-10 X 1 1/4	160	257.9
3/4-10 X 1 1/2	160	283.1
3/4-10 X 1 3/4	150	316.1
3/4-10 X 2	130	338.6
3/4-10 X 2 1/4	120	367.0
3/4-10 X 2 1/2	110	393.3
3/4-10 X 2 3/4	100	419.6
3/4-10 X 3	90	440.0
3/4-10 X 3 1/4	90	470.6
3/4-10 X 3 1/2	85	497.5
3/4-10 X 3 3/4	80	518.5
3/4-10 X 4	80	551.4
3/4-10 X 4 1/2	70	662.2
3/4-10 X 5	60	724.4
3/4-10 X 5 1/2	60	786.6
3/4-10 X 6	50	848.8
7/8-9 X 2 1/2	70	530.0
7/8-9 X 3	60	608.0
7/8-9 X 3 1/2	50	686.0
7/8-9 X 4	50	755.7
1-8 X 4	40	1130.0
1-8 X 5	35	1400.0
1-8 X 6	30	1572.0