



| DESCRIPTION AND SIZE | CARTON | Weight |
|--|----------|--------|
| | QUANTITY | Lbs/ M |
| PH TRUSS AB SMS H, T, ZINC & CLEAR CHROMATE | | |
| 6 X 3/8 | 25000 | 2.0 |
| 6 X 1/2 | 20000 | 2.3 |
| 6 X 5/8 | 18000 | 2.6 |
| 6 X 3/4 | 16000 | 3.1 |
| 6 X 1 | 13000 | 3.8 |
| 8 X 3/8 | 16000 | 3.0 |
| 8 X 1/2 | 13000 | 3.5 |
| 8 X 5/8 | 12000 | 4.0 |
| 8 X 3/4 | 10000 | 4.4 |
| 8 X 1 | 9000 | 5.5 |
| 8 X 1 1/4 | 8000 | 6.6 |
| 8 X 1 1/2 | 6000 | 7.6 |
| 10 X 1/2 | 9000 | 5.0 |
| 10 X 5/8 | 8000 | 5.7 |
| 10 X 3/4 | 8000 | 6.2 |
| 10 X 1 | 6000 | 7.5 |
| 10 X 1 1/4 | 5000 | 8.7 |
| 10 X 1 1/2 | 4500 | 10.0 |
| 1/4 X 3/4 | 4000 | 12.1 |
| 1/4 X 1 | 3000 | 14.4 |